


2/5

Fig.2



3/5





Fig.3



5/5

BEST AVAILABLE COPY

Fig.5

OmniBER XM: Session 4 (rtaylor) on kmtest03
File Tools Help

Ports: Add On Off
Configuration: Hide Show
Gating: Setup
Start Stop
Help

Overview
E+A
OH
Counts
GR-253
G.828
SRV-DIS
J1 Trace

Start Test
On selected port only

Port
Mismatches
203/1
204/1
0

Channel	Result	Length	Expected J1 Path Trace	Measured J1 Path Trace	Length
1,1	Pass	64 Bytes	Agilent OmniBER XM J7241A Port 0204/1-001	Agilent OmniBER XM J7241A Port 0204/1-001	64 Bytes
17,1	Fail	64 Bytes	Should fail	Agilent OmniBER XM J7241A Port 0204/1-049	64 Bytes
33,1	Pass	64 Bytes	Agilent OmniBER XM J7241A Port 0204/1-057	Agilent OmniBER XM J7241A Port 0204/1-057	64 Bytes
37,1	Not Tested	64 Bytes	Not tested yet		
41,1	Pass	64 Bytes	Agilent OmniBER XM J7241A Port 0204/1-121	Agilent OmniBER XM J7241A Port 0204/1-121	64 Bytes
45,1	Pass	64 Bytes	Agilent OmniBER XM J7241A Port 0204/1-133	Agilent OmniBER XM J7241A Port 0204/1-133	64 Bytes
49,1	Pass	64 Bytes	Agilent OmniBER XM J7241A Port 0204/1-145	Agilent OmniBER XM J7241A Port 0204/1-145	64 Bytes

Copy Expanded J1s
From:
Tx on 203/1
Current Rx
All Ports
Copy Now